

Port A as Output in Mode 0 : I/O mode selection Port 'A'

D ₇	D ₆	D ₅	D ₄
1	0	0	0

⇒

D ₇	D ₆	D ₅	D ₄
↓	↓	↓	↓
1	0	0	0

Port B as output in Mode 1 : Mode selc Port 'B'

D ₇	D ₂	D ₁
1	1	0

Port Cupper as output in Mode 0 :

D ₇	D ₃	D ₀
1	0	0

Above Instatation Result in CWR as

D ₇	D ₆	D ₅	D ₄	D ₃	D ₂	D ₁	D ₀
1	0	0	0	0	1	0	0